




## RIVER MILE 10.9 REMOVAL ACTION CAPPING OPERATIONS WEEKLY STATUS REPORT

### Summary of capping operations through week ending April 27, 2014


As of April 27, 100% of the dredged and capped area has been protected with a fabric and stone armoring layer. The final step of this Removal Action, application of a habitat layer over the armor stone, is expected to be completed by mid-May, 2014. The attached figure shows the section of RM 10.9 where the fabric and stone has been placed to date.

*All capping operations were conducted within acceptable water quality monitoring limits. Monitoring buoys #1 and #4 experienced calibration problems on 4/24/14 that were corrected by 4/25/14.*

### Capping Progress to Date Shown in Blue



## Real-Time Water Quality Monitoring





Water Quality Monitoring Locations